



Cofc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: N.A. Rudy et al. Attorney Docket No: DESS117969
Patent No: US 6,752,373 B1 Group Art Unit: 3754
Issued: June 22, 2004
Title: HIGH-SPEED FLUID JET BLOCKER

Certificate
SEP 21 2004
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Seattle, Washington 98101

ATTN: CERTIFICATE OF CORRECTION BRANCH
COMMISSIONER FOR PATENTS:

Enclosed is a Certificate of Correction, Form PTO 1050, for the above-identified U.S. Letters Patent. The errors in the printed patent listed on the enclosed form occurred at the corresponding locations in the application file listed below:

Column,	Line	Page,	Line
1	66	2	23
4	51	6	27
5	46	8	9
6	43	9	23
6	60	10	5
7	19	10	23
7	39	11	6
7	48	11	13
10 (Claim 1,	55 line 17)	2 (Claim 1, (Amendment	13 line 12) 1/23/04)

LAW OFFICES OF
CHRISTENSEN O'CONNOR JOHNSON KINDNESS^{LLC}
1420 Fifth Avenue
Suite 2800
Seattle, Washington 98101
206.682.8100


SEP 22 2004

Column,	Line	Page,	Line
14 (Claim 30,	3 line 22)	6 (Claim 26, (Amendment	26 line 14) 1/23/04)

Since the Certificate of Correction is necessitated by Patent and Trademark Office errors, no fee is required.

Respectfully submitted,

CHRISTENSEN O'CONNOR
JOHNSON KINDNESS^{PLLC}



Brian D. Krell
Registration No. 51,899
Direct Dial No. 206.695.1638

I hereby certify that this correspondence is being deposited with the U.S. Postal Service in a sealed envelope as first class mail with postage thereon fully prepaid and addressed to the Commissioner for Patents, ATTN: Certificate of Correction Branch, P.O. Box 1450, Alexandria, VA 22313-1450, on the below date.

Date:

9/14/2004



BDK:lac

LAW OFFICES OF
CHRISTENSEN O'CONNOR JOHNSON KINDNESS^{PLLC}
1420 Fifth Avenue
Suite 2800
Seattle, Washington 98101
206.682.8100

SEP 22 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,752,373 B1
DATED : June 22, 2004
INVENTOR(S) : N.A. Rudy et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>COLUMN</u>	<u>LINE</u>	<u>ERROR</u>
1	66	"WO 93/10950" should read --WO 93/10950--
4	51	"assemblies and 21," should read --assemblies 20 and 21,--
5	46	"1in" should read --130 in--
6	43	"mounting plate have recesses" should read --mounting plate 110 have recesses--
6	60	"arm 116 20 and" should read --arm 116 and--
7	19	"1and" should read --120 and--
7	39	"1may" should read --120 may--
7	48	"1of" should read --125 of--
10 (Claim 1, line 17)	55	"rotatable" should read --rotatably--

MAILING ADDRESS OF SENDER:

Christensen O'Connor Johnson Kindness^{PLLC}
1420 Fifth Avenue, Suite 2800
Seattle, WA 98101

PATENT NO. US 6,752,373 B1

No. of add'l copies
@ 50¢ per page

DESS\17969173A.DOC

⇒

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,752,373 B1
DATED : June 22, 2004
INVENTOR(S) : N.A. Rudy et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>COLUMN</u>	<u>LINE</u>	<u>ERROR</u>
14 (Claim 30, line 22)	3	"rotatable" should read --rotatably--

MAILING ADDRESS OF SENDER:

Christensen O'Connor Johnson Kindness^{PLLC}
1420 Fifth Avenue, Suite 2800
Seattle, WA 98101

PATENT NO. US 6,752,373 B1

No. of add'l copies
@ 50¢ per page
DESS\17969173A.DOC

⇒ _____